



RECREATIONAL VEHICLE SAFETY RECALL NOTICE

Original Notification Date October 14, 2010
NHTSA # 10V-478
Transport Canada # 2010-338
Keystone # 10-148

Recall Population

2011 Avalanche Fifth Wheels Production Dates: 8/17/2010 – 9/23/2010
VIN Range: 4YDF34028BE760285 - 4YDF33521BE760390

2011 Bullet Travel Trailers Production Dates: 8/16/2010 – 9/23/2010
VIN Range: 4YDT31B2XBD420916 - 4YDT21522BD421220

2011 Cougar Travel Trailers and Fifth Wheels Production Dates: 8/10/2010 – 9/23/2010 VIN Ranges:
Indiana - 4YDF32525B2503633 - 4YDF32223B2504574
Indiana X Lite - 4YDT27R25BV503756 - 4YDT30B29BV504939
High Country - 4YDF29628BA510298 - 4YDF29129BA510396
Oregon - 4YDT25R21BC503673 - 4YDT25R27BC504844

2011 Energy Travel Trailers Production Dates: 8/2/2010 – 8/25/2010
VIN Range: 4YDT28029BN830082 - 4YDT2802XBN830107

2011 Fuzion Travel Trailers and Fifth Wheels Production Dates: 8/24/2010 – 9/21/2010
VIN Range: 4YDF40525BF810617 - 4YDF30522BF810755

2011 Hornet and Hideout Travel Trailers Production Dates: 8/2/2010 – 9/23/2010 VIN Ranges
Indiana - 4YDT38B29B7201792 - 4YDT30R21B7202328
Oregon - 4YDT31R26BN201516 - 4YDT19F2XBN202211

2011 Laredo Travel Trailers and Fifth Wheels Production Dates: 8/13/2010 – 9/23/2010 VIN Ranges:
Travel Trailers - 4YDT30325BV601232 - 4YDT3032XBV601596
Fifth Wheels - 4YDF26525BE601277 - 4YDF26626BE601707

2011 Montana High Country Fifth Wheels Production Dates: 8/16/2010 – 9/22/2010
VIN Range: 4YDF33326BA740288 - 4YDF3432XBA740381

2011 Mountaineer Fifth Wheels Production Dates: 8/6/2010 – 9/23/2010
VIN Range: 4YDF34723BR730495 - 4YDF32625BR730682

2011 Outback Travel Trailers & Fifth Wheels Production Dates: 8/6/2010 – 9/23/2010 VIN Ranges:
Travel Trailer - 4YDT31223BB451694 - 4YDT30128BB452304
Sydney Edition - 4YDF32120BB630327 - 4YDF33029BB630382

2011 Passport Travel Trailers Production Dates: 8/12/2010 – 9/22/2010 VIN Ranges:
Indiana - 4YDT28522BT412032 - 4YDT28521BT412572
Oregon: 4YDT28521BX412273

2011 Raptor Travel Trailers and Fifth Wheels Production Dates: 8/6/2010 – 9/23/2010
VIN Range: 4YDF39127BR800635 - 4YDF3002XBR800853

2011 Retreat Travel Trailers Production Dates: 8/19/2010 – 9/7/2010
VIN Range: 4YDT39F24B7260605 - 4YDT39R27B7260724

2011 Residence Travel Trailer Production Date: 9/7/2010 VIN: 4YDT40522BW160163

2011 Sprinter Travel Trailers and Fifth Wheels Production Dates: 8/6/2010 – 9/23/2010
VIN Range: 4YDT25R22B1531798 - 4YDF24828B1532348

2011 Springdale Travel Trailers Production Dates: 8/12/2010 – 9/23/2010 VIN Ranges:
Plant 3 - 4YDT29121B3102756 - 4YDF27929B3103689
Plant 703 - 4YDT29525BW102820 - 4YDT29322BW103491

2011 Summerland Travel Trailers Production Dates: 8/13/2010 – 9/22/2010
VIN Range: 4YDT1892XB3150645 - 4YDT25722B3150833

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in the vehicles listed above and as a result is conducting a safety recall. We apologize for any inconvenience this action may cause; however the safety and continued satisfaction of our customers are of the utmost importance to us.

***Reason for
this recall***

It has been decided certain Atwood 35 Series Range Ovens manufactured before September 20, 2010 with model numbers beginning with RV1735, RV2135, or RA2135 and installed as original equipment on Keystone recreational vehicles may contain non-complying oven gas lines. A potential exists for a small fracture within the line delivering gas to the oven cavity burner. Such a fracture has a potential to leak when the oven burner has gas flowing to it and leads to an increased risk of propane gas build up. A propane leak, in the presence of an ignition source, could result in a fire and/or explosion causing property damage and/or personal injury.

Gas is only supplied through this line when the oven cavity is in use, and thus the potential does NOT exist for a gas leak while the range top burners only are lit or when the range oven controls are off. As such, until the range has been inspected and/or repaired, the oven cavity of all range ovens included in the recall population are not to be lit and used. You can continue to use the range top burners as normal.

***What we
will do***

Keystone has notified our dealers regarding this situation. The remedy is to isolate and perform a drop pressure test on the oven supply tube. If the tube leaks, it will be replaced. The service and parts required for this corrective action will be provided at no charge.

***What we need
you to do***

At your earliest convenience, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately one hour. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. If your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)