



**Keystone RV  
Company™**

**RECREATIONAL VEHICLE  
SAFETY RECALL NOTICE**

NHTSA: 15V-207  
 Transport Canada: 2015-255  
 Safety Advisory: 15-230  
 June 29, 2015

**Recall Population**

2015 Aspen Trail FH922580 – FH922659  
 2016 Aspen Trail GH920040 – GH920173  
 2015 Coleman FH933464 – FH933488  
 2016 Coleman GH930210 – GH930224  
 2016 Denali GP940000 – GP940084  
 2016 Razorback GH980000 – GH980005  
 2016 Rubicon GH985000 – GH985054  
 2016 Voltage GZ990000 – GZ990091  
 2015 Cougar F2509503 – F2509941  
 2016 Cougar G2500152 – G2500699  
 2015 Hideout FN207727 – FN207828  
 2016 Passport GX410088 – GX410176  
 2016 Sprinter G1530000 – G1530206  
 2016 Springdale GG100000 – GG100106

2015 Aspen Trail FY922586 – FY922645  
 2016 Aspen Trail GY920000 – GY920015  
 2015 Coleman FY933354 – FY933389  
 2015 Denali FP940887 – FP940973  
 2015 Razorback FH980073 – FH980081  
 2015 Rubicon FH985364 – FH985426  
 2015 Voltage FZ991414 – FZ991497  
 2015 Bullet FX425882 – FX426009  
 2015 Cougar FC509590 – FC509856  
 2016 Cougar GC500000 – GC500497  
 2016 Hideout GN200000 – GN200089  
 2015 Sprinter F1533056 – F1533227  
 2015 Springdale FG105075 – FG105283

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in the vehicles listed above. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for  
this recall***

It has been decided the vehicles identified in this recall population equipped with axles manufactured by Lippert Components Inc. (LCI) and Tru Ryde or Axle Tek 10” or 12” wheel hubs may have been manufactured with wheel studs which could break. If more than one wheel stud breaks and the vehicle is in motion, it could result in the separation of the wheel from the vehicle leading to an increased risk of property damage and/or vehicle crash.

***What we  
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to inspect the wheel hubs and replace if necessary. The service and parts required for this corrective action will be provided at no charge to you.

***What we  
need you to  
do***

As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 3 hours. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have  
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. If your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>).

