



RECREATIONAL VEHICLE RECALL NOTIFICATION

Original Notification Date March 18, 2005
NHTSA # 05V-083
Transport Canada # 05-067
Keystone # 05-053

REASON FOR THIS RECALL

Keystone RV Company has determined that a wiring defect may exist at or near the dimmer switch (s) in certain Cambridge Fifth Wheels manufactured by Keystone before March 4, 2005. The last six (6) digits of the potentially affected Cambridge Fifth Wheels are:

580001- 580088

WHAT KEYSTONE RV WILL DO

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. They stand ready to assist in addressing this condition by inspecting and repairing the wiring at no charge to you. At your earliest convenience, please make an appointment to have your Cambridge Fifth Wheel serviced by your dealership. The labor time necessary to perform this correction is approximately 1.5 hours; however, it may be necessary to order parts so the Fifth Wheel may not be available the same day.

Your dealer is best equipped to obtain parts and provide service to ensure your Fifth Wheel is corrected as promptly as possible. If, however, you take your Fifth Wheel to your dealer on the agreed upon service date, and they do not remedy the condition within a reasonable amount of time, please contact Keystone Customer Service by calling 1-866-425-4369.

Alert: Continued use of the Cambridge Fifth Wheel without having the preventative actions completed immediately could lead to fire, personal injury or death.

We regret any inconvenience this action may cause you. As we are sure you will appreciate, the safety of our customers and the quality of our products are of the utmost importance to Keystone.

Should you have any questions or concerns regarding this correspondence, please feel free to contact one of our Customer Service Representatives at 866-425-4369. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time period, you may also submit a written complaint to:

**Administrator
National Highway Traffic Safety Administration
400 Seventh Street SW
Washington DC, 20590**

You may also call at 1-888-DASH-2-DOT (1-888-327-4236). Washington residents use 1-202-366-0123.

**2642 Hackberry Drive – Goshen, IN 46526
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com**