



**RECREATIONAL VEHICLE SAFETY RECALL NOTICE**

Original Notice Date: December 27, 2007  
US Safety Recall: 07V-585  
Canada Recall: 07-383  
Service Advisory: 07-096

**Models Included:** Challenger 32SAT Fifth Wheel  
Everest 320T Fifth Wheel

**Serial Numbers:** 2007 Everest 4YDF320207E771020 - 4YDF320227E771729  
2008 Everest 4YDF320248E770034 - 4YDF320288E770473  
2007 Challenger 4YDF32S297E750776 - 4YDF32S227E751543  
2008 Challenger 4YDF32S278E750020 - 4YDF32S238E750550

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model year 2007 and 2008 Everest fifth-wheels and 2007 and 2008 Challenger fifth-wheel recreational vehicles. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for this recall***

The vehicles subject to this recall campaign may have the slide-room propane line installed too close to the tire during vehicle assembly. The propane line may become damaged as a result of contact with the tire. A propane leak, in the presence of an ignition source, could result in a fire and/or explosion causing property damage and/or personal injury.

***What we will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to replace the propane hose with one of a shorter length and also shorten the hose support to move the hose away from the tire. The service and parts required for this corrective action will be provided at no charge to you.

***What we need you to do***

At your earliest convenience, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately one and a half hours. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. If your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

If after contacting your dealer and Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)

In Canada, you may also submit a written complaint to: Head of Recalls Road Safety and Motor Vehicle Regulation, Transport Canada, 2780 Sheffield Rd., Ottawa, Ontario K1B 3V9. You may also call at 1-613-993-9851.

Thank you for your attention and cooperation in this matter.

Sincerely,

**KEYSTONE RV COMPANY**

Rick Deisler  
Sales & Service Manager

cc: National Highway Traffic Safety Administration (NHTSA)



**2642 Hackberry Drive – Goshen, IN 46526**  
**Phone: (574) 535-2100 – Fax: (574) 535-2199**  
**[www.keystonerv.com](http://www.keystonerv.com)**