



**RECREATIONAL VEHICLE SAFETY RECALL NOTICE**

Original Notice Date: July 31, 2007  
Safety Recall: 07V-329  
Canadian Recall: 07-213  
Service Advisory: 07-085

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in certain model year 2007 and 2008 Montana Fifth Wheels. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

**MODELS AND SERIAL NUMBERS AFFECTED**

**Models Included: 2007 & 2008 Montana Fifth Wheels with Aluminum Wheels manufactured between April 27, 2007 and May 1, 2007. Note: Some units were repaired at the factory prior to shipment. Only those listed below are involved in this recall.**

VINS:	<u>2007 Montanas</u>	<u>2008 Montanas</u>		
	4YDF3482274704635	4YDF3402874704649	4YDF3502X84700061	4YDF3292284700072
	4YDF3402X74704636	4YDF3582174704650	4YDF3502184700062	4YDF3502684700073
	4YDF3482674704637	4YDF3402674704651	4YDF3292184700063	4YDF3292684700074
	4YDF3402374704638	4YDF3582574704652	4YDF3502584700064	4YDF3502X84700075
	4YDF3582274704639	4YDF3402X74704653	4YDF3292584700065	4YDF3502184700076
	4YDF3402174704640	4YDF3582974704654	4YDF3502984700066	4YDF3292184700077
	4YDF3582074704641	4YDF3402374704655	4YDF3292984700067	4YDF3652784700078
	4YDF3402574704642	4YDF3582274704656	4YDF3502284700068	4YDF3292584700079
	4YDF3582474704643	4YDF3402774704657	4YDF3502484700069	4YDF3652584700080
	4YDF3582674704644	4YDF3582674704658	4YDF3292984700070	4YDF3292384700081
	4YDF3402074704645	4YDF3402074704659	4YDF3502284700071	4YDF3652984700082
	4YDF3582X74704646	4YDF3582474704660		
	4YDF3402474704647	4YDF3582674704661		
	4YDF3582374704648			

**Reason for this recall** The vehicles subject to this recall campaign may have excess paint at the wheel and the hub face mounting surface. The excess paint may cause the lug nuts to loose torque over time and could ultimately cause wheel separation if the torque is not maintained. Wheel separation could result in poor vehicle handling and increased risk of property damage and a vehicle crash.

**What we will do** Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to remove the wheels, remove the paint from the hub face wheel mounting surface and then reinstall and torque the wheels to the proper specification. The service and parts required for this corrective action will be provided at no charge to you.

**What we need you to do** At your earliest convenience, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately 3 hours. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

**If you have questions** Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. If your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

In the USA, if your dealer fails or is unable to remedy this defect without charge and within a reasonable time period, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)

In Canada, you may also submit a written complaint to: Head of Recalls Road Safety and Motor Vehicle Regulation, Transport Canada, 2780 Sheffield Rd., Ottawa, Ontario K1B 3V9. You may also call at 1-613-993-9851.

Thank you for your attention and cooperation in this matter.

Sincerely,  
**KEYSTONE RV COMPANY**  
Rick Deisler  
Sales & Service Manager

**2642 Hackberry Drive – Goshen, IN 46526**  
**Phone: (574) 535-2100 – Fax: (574) 535-2199**  
[www.keystonerv.com](http://www.keystonerv.com)

