



RECREATIONAL VEHICLE RECALL NOTIFICATION

Original Notification Date December 10, 2004
NHTSA # 04V-577
Transport Canada # 04-443
Keystone # 05-048

Recall Population:

2005 Outback Sydney Edition 30RLS Travel Trailers
Production Dates 9/30/2004 – 10/15/2004
VIN Range: 4YDT30R245G912053 - 4YDT30R295G912369

REASON FOR THIS RECALL

It has been determined that a wire-routing defect may exist at or near the gray holding tank in the vehicles listed above. Under certain circumstances, the misrouted wires may become pinched by the heat plenum framing. Continued use of the unit without having the preventative actions completed could result in personal injury or property damage.

WHAT KEYSTONE RV WILL DO

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. They stand ready to assist in addressing this condition by rerouting the wires at no charge to you. At your earliest convenience, please make an appointment to have your unit corrected by your dealership.

We apologize for any inconvenience this situation may cause. As we are sure you will appreciate, the safety of our customers and the quality of our products are of the utmost importance to us.

IF YOU HAVE QUESTIONS

Should you have any questions or concerns regarding this correspondence, please feel free to contact one of our Customer Service Representatives at 866-425-4369. If your dealer fails or is unable to remedy this defect without charge and within a reasonable time period, you may submit a written complaint to:

**Administrator
National Highway Traffic Safety Administration
400 Seventh Street SW
Washington DC, 20590**

You may also call at 1-888-DASH-2-DOT (1-888-327-4236). Washington residents use 1-202-366-0123.

**2642 Hackberry Drive – Goshen, IN 46526
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com**