



**Keystone RV
Company**

**RECREATIONAL VEHICLE
SAFETY RECALL NOTICE**

NHTSA: 14V-146
Transport Canada: 2014-099
Safety Advisory: 14-205
April 17, 2014

Recall Population

2014 Bullet TT ED424375 – ED424420
2014 Cougar FW E2507478
2014 Springdale TT E3103521 – E3103567
2014 Summerland TT E3151608 – E3151636

Keystone RV Company has decided that a defect which relates to motor vehicle safety exists in the vehicles listed above. As a result, Keystone RV is conducting a safety recall. We apologize for any inconvenience this action may cause you; however your safety and continued satisfaction are of the utmost importance to us.

***Reason for
this recall***

It has been decided that frames built with 4¼ spring hanger, with a build date of 2/13/2014 to 2/24/2014 manufactured by Lippert Components at their plant in Goshen Indiana, may have a material quality defect in the frame spring hangers causing the material to be brittle and subject to fracture under stress. If the hanger has the defect, it may fail during travel leading to an increased risk of loss of control and vehicle crash.

***What we
will do***

Keystone representatives have been in contact with the staff at your selling dealership regarding this situation. The remedy is to inspect the spring hanger and replace if the defect exists with a spring hanger supplied by Keystone. The service and parts required for this corrective action will be provided at no charge to you.

***What we need
you to do***

As soon as possible, please make an appointment to have your RV serviced by your dealership. The labor time to perform this correction is approximately two to three hours. Please ask your dealer if you wish to know how much additional time will be needed to schedule and process your RV for this repair.

***If you have
questions***

Your dealer is best equipped to obtain parts and provide service to ensure your RV is corrected as promptly as possible. If your dealer is unable to assist or if you take your RV to your dealer on the agreed service date, and the dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

If after contacting Keystone Customer Service you are still not satisfied we have done our best to remedy this situation, you may also submit a written complaint to: Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)



**PO Box 2000 – Goshen, IN 46527-2000
Phone: (866) 425-4369 – Fax: (866) 273-1451
www.keystonerv.com**