



RECREATIONAL VEHICLE SAFETY RECALL NOTICE

Original Notice Date: February 15, 2006

Safety Recall: 05V-424

Canadian Recall: 05-287

Service Advisory: 05-060

Tredit Tire & Wheel Company, working in conjunction with Keystone RV Company, has decided that a defect which relates to motor vehicle safety exists with 16" Chrome-plated wheels installed on certain 2005 & 2006 Mountaineer, Cougar, Sprinter & Tail-Gator travel trailers and fifth wheels. The manufacture dates and last six (6) digits of the Vehicle Identification Numbers (VIN) of the potentially affected recreational vehicles are:

Mountaineer:	2/16/2005-8/31/2005	VIN's:	706028-707430
Cougar:	2/16/2005-9/14/2005	VIN's:	064082-065592
Sprinter:	2/16/2005-9/1/2005	VIN's:	222037-224800
Tail-Gator:	3/11/2005-6/24/2005	VIN's:	852749-853987

WARNING! Continued use of the Keystone RV without having this preventative action completed immediately could lead to a wheel separation, loss of control of the vehicle, which could result in a crash, property damage or personal injury.

WHAT TREDIT TIRE & WHEEL COMPANY WILL DO

Tredit Tire & Wheel Company is administering this recall and Tredit representatives have been in contact with the staff at your selling dealership regarding this situation. The Dealers stand ready to assist you in addressing this condition by inspecting the wheels on your recreational vehicle to determine if it is affected. If affected, the Dealer will order replacement rims and install them with proper torque and reviewing/demonstrating proper torque techniques and Owner maintenance requirements to you.

At your earliest convenience, please make an appointment to have your Travel Trailer or Fifth Wheel serviced by your dealership. The recreational vehicle will need to be at the dealer to perform this service correction approximately one (1) day after parts arrive.

Inquiries regarding this recall can be directed to your dealer. If your dealer is unable to assist, please contact Tredit Tire & Wheel Company at 1-866-443-9907. If you take your Travel Trailer or Fifth Wheel to your dealer on the agreed service date, and the Dealer does not remedy the condition within a reasonable amount of time, or without charge to you, please contact Keystone Customer Service by calling 1-866-425-4369.

In the USA, if your dealer fails or is unable to remedy this defect without charge and within a reasonable time period, you may also submit a written complaint to Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE, Washington, DC 20590. You may call the toll-free Vehicle Safety Hotline at 1-888-327-4236 (TTY: 1-800-424-9153; or go to <http://www.safercar.gov>.)

In Canada, you may also submit a written complaint to: Head of Recalls Road Safety and Motor Vehicle Regulation, Transport Canada, 2780 Sheffield Rd., Ottawa, Ontario K1B 3V9. You may also call at 1-613-993-9851.

We regret any inconvenience this action may cause you. As we are sure you will appreciate, the safety of our customers and the quality of our products are of the utmost importance to us.

Thank you for your attention and cooperation in this matter.

Sincerely,

KEYSTONE RV COMPANY

Rick Deisler
Sales & Service Manager

2642 Hackberry Drive – Goshen, IN 46526
Phone: (574) 535-2100 – Fax: (574) 535-2199
www.keystonerv.com